

Clinical Medical Image Library

Image 1:016

Drive Line Infection and Colonic Erosion: A Rare Complication of Left Ventricular Assist Device Placement Demonstrated on PET/CT

Abstract

Left ventricular assist device (LVAD) placement is now commonly performed as both bridge to transplant and as destination therapy in end stage cardiomyopathy with high associated prevalence of sepsis (up to 58%) and mortality (up to 44%). Recent evidence indicates that physiologic imaging with scintigraphy is more sensitive than anatomic imaging for early diagnosis of driveline and pump infections. Additionally colonic perforation is a rare but likely underdiagnosed complication which contributes to post-placement morbidity. Here we present a case report of LVAD drive line infection associated with colonic perforation, diagnosed on ¹⁸FDG-PET/CT.

Keywords

LVAD infection, Colonic perforation, PET/CT



Figure 1

PET/CT demonstrating isolated drive line infection - A 79 year old with non-ischemic cardiomyopathy status post destination therapy with left ventricular assist device, presented multiple times in the year following device placement with hypotension, fever, chills, leukocytosis and abdominal pain. 2D cardiac echo and CT abdomen/pelvis with contrast were performed but no source of infection was identified. After 8 months of treatment failure with escalating intravenous antibiotics, whole body ¹⁸FDG-PET/CT demonstrated increased activity diffusely along the drive line (blue arrows). Notice the absence of FDG uptake within or surrounding the main LVAD pump (white arrow) on planar or fused images. These two findings in conjunction are consistent with isolated drive line infection of the LVAD device. There is a high prevalence of device-related infections in LVAD patients [1] with sepsis being the leading complication in this population [2] and accounting for more than twice the number of deaths compared to device failure [3]. Infection typically involves the driveline which connects the LVAD pump to its external power source and can present clinically with fever, chills, leukocytosis, erythema and purulent drainage at the exit site [4]. Less commonly, infection can extend up to the subcutaneous recess where the LVAD pump is housed leading to pump pocket infection, in which case deep tissue tenderness may also be present [5]. Anatomic imaging (CT, Ultrasound) is sensitive in identifying fluid collections, if any, associated with the infection site. However there is evidence that scintigraphy is more sensitive in identifying and localizing infection, especially early on in its course [6]. This case illustrates the utility of physiologic imaging with PET/CT to diagnose and localize LVAD drive line infection even in the setting of persistent negative anatomic imaging and associated rare complication of colonic erosion with the drive line.

Information Kanchan Kulkarni*

Nuclear Endocrinology, Medstar Washington Hospital Center, USA

*Correspondence: Kanchan Kulkarni, M.D, Director, Nuclear Endocrinology, Associate Professor, Georgetown University Internal Medicine, Nuclear Medicine Staff Attending, Medstar Washington Hospital Center 110 Irving Street, NW, Suite GB01, Washington, DC 20010, USA, Tel: 202 877 5313, Fax: 202 877 6601, Email: Kanchan.Kulkarni@medstar.net **Citation:** Kulkarni K (2015) Drive Line Infection and Colonic Erosion: A Rare Complication of Left Ventricular Assist Device Placement Demonstrated on PET/CT. Clin Med Img Lib 1:016

Published: November 23, 2015

Copyright: © 2015 Kulkarni K. This is an open-access content distributed under the terms of the Creative Commons Attribution License, which permits unrestricted use, distribution, and reproduction in any medium, provided the original author and source are credited.





Figure 2

PET/CT demonstrating colonic erosion of the drive line - Axial images demonstrate erosion of the LVAD drive line into the superior wall of the transverse colon and asymmetrically increased activity within the adjacent segment of colon. This was subsequently confirmed during open surgical exploration of the drive line infection for which the patient received a partial colectomy. Extension of the LVAD driveline into the intestinal tract, causing erosion or perforation, is rare, with just a few isolated cases previously reported in medical literature [7-10]. In the case reported by Herman et al. [7], a similar clinical course was noted, with multiple admissions for fever, chills, hypotension and bacteremia in the context of normal anatomic imaging for a prolonged period of time. The diagnosis was made after CT chest demonstrated gas within the LVAD pocket on post-operative day 234 and colonic perforation was discovered during the emergent exploratory laparotomy that followed. This case demonstrates that scintigraphy with PET/CT can not only be utilized for diagnosis and localization of LVAD infection but can also assist in recognition of the rare but under-recognized complication of colonic erosion.

References

- 1. Miller LW, Pagani FD, Russell SD, John R, Boyle AJ, et al. (2007) Use of a continuous-flow device in patients awaiting heart transplantation. N Engl J Med 357: 885-896.
- 2. Didisheim P, Rose EA, Long JW, Holman WL, Burns G, et al. (2001) Infection with clinical ventricular assist devices: clinical therapy. ASAIO J 47: 195-196.
- Rose EA, Gelijns AC, Moskowitz AJ, Heitjan DF, Stevenson LW, et al. (2001) Long-term use of a left ventricular assist device for end-stage heart failure. N Engl J Med 345: 1435-1443.
- 4. Maniar S, Kondareddy S, Topkara VK (2011) Left ventricular assist device-related infections: past, present and future. Expert Rev Med Devices 8: 627-634.
- 5. Holman WL, Rayburn BK, McGiffin DC, Foley BA, Benza RL, et al. (2003) Infection in ventricular assist devices: prevention and treatment. Ann Thorac Surg 75: S48-57.
- Litzler PY, Manrique A, Etienne M, Salles A, Edet-Sanson A, et al. (2010) Leukocyte SPECT/CT for detecting infection of left-ventricular-assist devices: preliminary results. J Nucl Med 51: 1044-1048.
- Herman SC, Muehlschlegel JD, Couper GS, Kelly E (2010) Colonic perforation from left ventricular assist device: a rare complication. Interact Cardiovasc Thorac Surg 11: 369-370.
- 8. Hou JK, Hampel H, Lukens FJ (2005) Gastric ulceration and perforation as a complication of a left ventricular assist device. Gastrointest Endosc 61: 629-631.
- 9. Yannopoulos D (2007) Subacute gastric perforation caused by a left ventricular assist device. World J Gastroenterol 13: 3253-3254.
- 10. Phillips WS, Burton NA, Macmanus Q, Lefrak EA (1992) Surgical complications in bridging to transplantation: the Thermo Cardiosystems LVAD. Ann Thorac Surg 53: 482-485.